

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, September 25, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13539+00 – 13551+50 STA 13562+63 – 13575+21 STA 13632+25 – 13645+00	Weather:	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-II8, S-II7, S-II9, S-II11, S-II12, S-GH6, W-GH2 and S-E28.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Friday, September 25, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, September 25, 2020

**Figure 1: STA 13540+00** – Controls in place and functioning properly.

☼ 269°W (T) ● 37°5'28"N, 79°59'28"W ±16ft ▲ 1293ft



**Figure 2: STA 13575+00** – Controls in place and functioning properly.

☼ 270°W (T) ● 37°5'34"N, 79°58'48"W ±16ft ▲ 1329ft



**Figure 3: Stream S-II9** – Controls in place and functioning properly around S-II9 crossing.

☼ 78°E (T) ● 37°5'28"N, 79°59'26"W ±213ft ▲ 1284ft



**Figure 4: STA 13638+00** – Controls in place and functioning properly.

☼ 299°NW (T) ● 37°5'21"N, 79°57'44"W ±16ft ▲ 1180ft

