

## FIELD INSPECTION REPORT

|                                |                                                |                  |                             |
|--------------------------------|------------------------------------------------|------------------|-----------------------------|
| Project Name:                  | Mountain Valley Pipeline                       | Inspector:       | Marshall Willis             |
| Inspection Date:               | Thursday, September 24, 2020                   | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H:<br>Montgomery County | STA 12190+85 – 12214+00<br>ATWS 1446/1062/1375 | Weather:         | Dry                         |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C21 and S-OO11.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, September 24, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, September 24, 2020

**Figure 1: Stream S-C21** – Controls in place and functioning properly around Bradshaw Creek crossing.

☉ 44°NE (T) ☉ 37°14'6"N, 80°15'34"W ±25854ft ▲ 1289ft



**Figure 2: STA 12199+00** – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 34°NE (T) ☉ 37°15'7"N, 80°15'26"W ±669ft ▲ 1298ft



**Figure 3: STA 12200+00** – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 59°NE (T) ☉ 37°15'8"N, 80°15'24"W ±2004ft ▲ 1301ft



**Figure 4: STA 12210+00** – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 125°SE (T) ☉ 37°15'10"N, 80°15'13"W ±32ft ▲ 1425ft

