

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 23, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14170+00 – 14200+00 ATWS 1479/1480/1481/521	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-KL52 and S-KL54.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, September 23, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 23, 2020

Figure 1: STA 14173+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 33°NE (T) ☉ 37°3'27"N, 79°50'44"W ±16ft ▲ 1022ft



Figure 2: STA 14182+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 71°E (T) ☉ 37°3'32"N, 79°50'33"W ±16ft ▲ 964ft



Figure 3: Stream S-KL54 – Controls in place and functioning properly around S-KL54 crossing.

☉ 71°E (T) ☉ 37°3'19"N, 79°50'31"W ±3970ft ▲ 924ft



Figure 4: STA 14198+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 145°SE (T) ☉ 37°3'36"N, 79°50'18"W ±16ft ▲ 996ft

