

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, September 18, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15296+00 – 15370+62 ATWS 389/389A/391/392/492/492A	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C4, S-C3, S-H13 and W-H5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Friday, September 18, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, September 18, 2020

Figure 1: STA 15302+00 – Controls in place and functioning properly.

☉ 142°SE (T) ● 36°55'54"N, 79°31'46"W ±32ft ▲ 742ft



15302

Figure 2: STA 15324+00 – Controls in place and functioning properly.

☉ 145°SE (T) ● 36°55'44"N, 79°31'23"W ±16ft ▲ 673ft



15324

Figure 3: STA 15335+00 – Controls in place and functioning properly.

☉ 125°SE (T) ● 36°55'37"N, 79°31'12"W ±32ft ▲ 769ft



15335

Figure 4: STA 15360+00 – Controls in place and functioning properly.

☉ 110°E (T) ● 36°55'23"N, 79°30'51"W ±32ft ▲ 762ft



15360