

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, September 17, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12448+00 – 12464+25 STA 12480+75 – 12485+00 MVP-MLV-AR-28	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-CD12b and W-KL58.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, September 17, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, September 17, 2020

Figure 1: STA 12483+00 – Controls in place and functioning properly. Area stabilized with erosion matting and hydro-mulch.

☉ 146°SE (T) ☉ 37°13'24"N, 80°12'7"W ±16ft ▲ 1568ft



Figure 2: STA 12480+00 – Controls in place and functioning properly. Area stabilized with erosion matting and hydro-mulch.

☉ 6°N (T) ☉ 37°13'55"N, 80°12'7"W ±213ft ▲ 1230ft



Figure 3: STA MVP-MLV-AR-28 – Controls in place and functioning properly.

☉ 269°W (T) ☉ 37°13'24"N, 80°12'8"W ±16ft ▲ 1530ft



Figure 4: STA 12464+00 – Controls in place and functioning properly.

☉ 118°SE (T) ☉ 37°13'44"N, 80°12'14"W ±32ft ▲ 1227ft

