

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 16, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15063+85 – 15142+66 ATWS 382/1288/1287/383/384	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G11, S-G9, S-G8, S-Q15, S-A6 and S-H11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, September 16, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 16, 2020

Figure 1: STA 15064+00 – Controls in place and functioning properly.

☉ 128°SE (T) ☉ 36°57'47"N, 79°35'35"W ±16ft ▲ 915ft



Figure 2: Stream S-G11 – Controls in place and functioning properly around stream S-G11 crossing. Area stabilized with straw.

☉ 115°SE (T) ☉ 36°57'44"N, 79°35'26"W ±16ft ▲ 890ft



Figure 3: STA 15081+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 124°SE (T) ☉ 36°57'42"N, 79°35'16"W ±16ft ▲ 895ft



Figure 4: Stream S-G8 – Controls in place and functioning properly around stream S-G8 crossing.

☉ 358°N (T) ☉ 36°57'26"N, 79°35'0"W ±16ft ▲ 844ft

