

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, November 18, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13342+67 – 13415+51 ATWS 1352	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☐ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ3, W-IJ2-PSS, W-IJ1, S-IJ2, S-IJ1, S-RR11, S-RR09, and S-RR08.

Routine Maintenance: (72-Hour Deadline from Notification)
STA 13408+00: Sump maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: **Wednesday, November 18, 2020**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, November 18, 2020

Figure 1: STA 13413+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

☉ 289°W (T) ☉ 37°5'34"N, 80°1'39"W ±16ft ▲ 1459ft



Figure 2: STA 13408+00 – Sump maintenance needed.

☉ 355°N (T) ☉ 37°5'36"N, 80°1'45"W ±16ft ▲ 1575ft



Figure 3: STA 13385+00 – Controls in place and functioning properly. Travel lane active and disturbed.

☉ 137°SE (T) ☉ 37°3'25"N, 79°55'50"W ±13156ft ▲ 1640ft



Figure 4: STA 13331+00 – Controls in place and functioning properly. Travel lane active and disturbed

☉ 135°SE (T) ☉ 37°6'6"N, 80°2'27"W ±98ft ▲ 1494ft

