

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, November 9, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15693+89 – 15741+92 STA 15760+91 – 15826+77 MVP-PI-338.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-B6, S-B8, S-B9, S-DD4, S-KL27 and S-C1.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 15742+00: P1 maintenance needed along the south side of ATWS 499A.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, November 9, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, November 9, 2020

Figure 1: STA 15697+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 144°SE (T) ● 36°52'46"N, 79°25'15"W ±16ft ▲ 787ft



Figure 2: STA 15717+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 114°SE (T) ● 36°52'36"N, 79°24'55"W ±32ft ▲ 783ft



Figure 3: STA 15742+00 – P1 maintenance needed along south side of ATWS 499A.

☼ 187°S (T) ● 36°52'43"N, 79°24'2"W ±67490ft ▲ 852ft



Figure 4: STA 15815+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 331°NW (T) ● 36°51'35"N, 79°23'40"W ±98ft ▲ 824ft

