

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, November 5, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12807+43 MVP-RO-283 ATWS 1447/1448	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | | Yes | No | N/A |
|----|---|--------------------------|-------------------------------------|-------------------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

1. Investigation of MVP-RO-283 and ROW in surrounding area as a result of turbidity monitoring spike at USGS station (0205373422) on Bottom Creek.
2. ROW in this area has no ground disturbance to date and only felled trees.
3. MVP-RO-283 has not been improved to date and is not being used by construction traffic.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, November 5, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 5, 2020

Figure 1: STA 12807+43 – No ground disturbance to date. Trees felled. Looking N down ROW.

☉ 5°N (T) ☉ 37°10'1"N, 80°8'18"W ±32ft ▲ 2720ft



Figure 2: STA 12807+43 – No ground disturbance to date. Trees felled. Looking SW down ROW.

☉ 208°SW (T) ☉ 37°10'1"N, 80°8'18"W ±16ft ▲ 2713ft



Figure 3: MVP-RO-283 – Access road has not been installed or utilized by construction traffic. No active ground disturbance.

☉ 53°NE (T) ☉ 37°10'1"N, 80°8'15"W ±6227ft ▲ 2781ft



Figure 4: MVP-RO-283 – Access road has not been installed or utilized by construction traffic. No active ground disturbance.

☉ 227°SW (T) ☉ 37°10'9"N, 80°7'45"W ±32ft ▲ 2711ft

