

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, November 4, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12190+85 – 12236+71 MVP-MN-276.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-OO11 and S-C21.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 12217+62: SSF maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: **Wednesday, November 4, 2020**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, November 4, 2020

Figure 1: STA 12228+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 265°W (T) ☉ 37°14'18"N, 80°13'19"W ±25043ft ▲ 1271ft



Figure 2: STA 12217+62 – Maintenance needed on SSF.

☉ 339°N (T) ☉ 37°15'10"N, 80°15'3"W ±98ft ▲ 1750ft



Figure 3: STA 12212+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 267°W (T) ☉ 37°15'11"N, 80°15'12"W ±32ft ▲ 1490ft



Figure 4: STA 12200+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 55°NE (T) ☉ 37°15'8"N, 80°15'24"W ±16ft ▲ 1311ft

