

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, November 2, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14649+67 – 14719+41 MVP-FR-321	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H40, W-H17, S-H37, W-H16, W-H15, S-H36, W-H14, S-H34, S-H32 and W-H11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, November 2, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, November 2, 2020

Figure 1: STA 14670+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 95°E (T) ● 36°59'17"N, 79°43'5"W ±16ft ▲ 980ft



Figure 2: STA 14686+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 58°NE (T) ● 36°59'16"N, 79°42'46"W ±16ft ▲ 946ft



Figure 3: STA 14698+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 103°E (T) ● 36°59'17"N, 79°42'32"W ±16ft ▲ 946ft



Figure 4: STA 14708+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 77°E (T) ● 36°59'17"N, 79°42'20"W ±16ft ▲ 914ft

