

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, October 28, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14333+27 – 14454+22 MVP-FR-315	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-A36, S-A38, S-A40, W-DD1, S-A41, S-G36, S-KL17, S-GH37, S-GH39, S-GH40, S-GH44 and S-GH16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, October 22, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 22, 2020

Figure 1: STA 14337+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 121°SE (T) ☉ 37°2'18"N, 79°48'12"W ±541ft ▲ 1158ft



14337

Figure 2: Stream S-A38 – Controls in place and functioning properly around S-A38 crossing.

☉ 56°NE (T) ☉ 37°2'10"N, 79°47'59"W ±16ft ▲ 1084ft



S-A38

Figure 3: STA 14419+00 – Controls in place and functioning properly.

☉ 107°E (T) ☉ 37°1'29"N, 79°46'16"W ±7418ft ▲ 1065ft



14419

Figure 4: STA 14433+00 – Controls in place and functioning properly.

☉ 128°SE (T) ☉ 37°1'44"N, 79°46'30"W ±32ft ▲ 1035ft



14433