

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, December 22, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County Pittsylvania County	STA 14970+00 – 14995+20 STA 15205+00 – 15229+50 MVP-FR-324	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-D7 and W-MM17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, December 22, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, December 22, 2020

Figure 1: STA 15222+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 125°SE (T) LAT: 36.938591 LON: -79.555044 ±16ft ALT: 819ft



15222

Figure 2: STA 15209+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 288°W (T) LAT: 36.939722 LON: -79.559166 ±16ft ALT: 824ft



15209

Figure 3: STA 14996+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 84°E (T) LAT: 36.964633 LON: -79.615137 ±164ft ALT: 909ft



14996

Figure 4: STA 15213+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 121°SE (T) LAT: 36.939863 LON: -79.557595 ±16ft ALT: 841ft



15213