

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, December 18, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12119+17 – 12155+00 MVP-MN-272/273	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-C5, W-C6, S-KL5, W-KL6, W-C12, S-C33, S-C36, W-C11, S-MM31 and S-C29.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, December 18, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, December 18, 2020

Figure 1: STA 12150+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 294°NW (T) LAT: 37.254928 LON: -80.272211 ±16ft ALT: 1534ft



Figure 2: STA 12138+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 116°SE (T) LAT: 37.257680 LON: -80.276356 ±1686ft ALT: 1427ft



Figure 3: STA 12133+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 286°W (T) LAT: 37.256431 LON: -80.277685 ±98ft ALT: 1430ft



Figure 4: STA 12120+00 – Controls in place functioning properly.

BRG: 84°E (T) LAT: 37.257264 LON: -80.282002 ±16ft ALT: 1442ft

