

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 17, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13690+91 – 13748+05 STA 13811+81 – 13840+00 MVP-FR-302	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E28, W-E7, W-E8, S-E28, S-EF4 and S-C14.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, December 17, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 17, 2020

Figure 1: Stream S-E28 – Controls in place functioning properly around S-E28 crossing

BRG: 86°E (T) LAT: 37.082915 LON: -79.945826 ±16ft ALT: 1126ft



Figure 2: STA 13712+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 172°S (T) LAT: 37.081867 LON: -79.941946 ±16ft ALT: 1231ft



Figure 3: STA 13832+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 167°S (T) LAT: 37.064889 LON: -79.923038 ±541ft ALT: 1158ft



Figure 4: STA 13819+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 328°NW (T) LAT: 37.068112 LON: -79.922239 ±32ft ALT: 1125ft

