

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, December 15, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12994+00 – 13018+86 STA 12680+00 – 12710+00 MVP-RO-280	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 12685+50: SSF maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, December 15, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, December 15, 2020

Figure 1: STA 13012+00 – Controls in place functioning properly.
 ☼ 330°NW (T) ● 37°7'33"N, 80°7'31"W ±32ft ▲ 2735ft



Figure 2: STA 12995+00 – Controls in place functioning properly.
 ☼ 126°SE (T) ● 37°7'43"N, 80°7'47"W ±16ft ▲ 2665ft



Figure 3: STA 12685+50 – SSF maintenance needed.

BRG: 280°W (T) LAT: 37.192338 LON: -80.158654 ±16ft ALT: 3716ft



Figure 4: STA 12693+00 – Controls in place and functioning properly.

BRG: 125°SE (T) LAT: 37.182516 LON: -80.139903 ±23242ft ALT: 3723ft

