

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, December 11, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12960+00 – 12981+86 MVP-RO-288/281	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF32.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, December 11, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, December 11, 2020

Figure 1: STA 12973+00 – Controls in place functioning properly. Area stabilized with Earth-Guard.

☉ 118°SE (T) ☉ 37°7'50"N, 80°8'13"W ±98ft ▲ 2776ft



Figure 2: STA 12965+00 – Controls in place functioning properly. Area stabilized with erosion control matting.

☉ 11°N (T) ☉ 37°7'56"N, 80°8'13"W ±32ft ▲ 2717ft



Figure 3: MVP-RO-281 – Controls in place and functioning properly. Contractor installing access road.

☉ 250°W (T) ☉ 37°10'55"N, 80°8'42"W ±98ft ▲ 2962ft



Figure 4: MVP-RO-281 – Controls in place and functioning properly. Contractor installing access road.

☉ 356°N (T) ☉ 37°10'42"N, 80°8'0"W ±20286ft ▲ 3086ft

