

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 9, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15496+70 – 15619+48 ATWS 820/819/813/1445	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-CC13, W-CC2-PEM, S-C14, S-MM8, W-MM5, S-CC15, S-CC8, S-CC5, S-CC9, S-CC10, S-MM10 S-CC11, W-MM9, S-CC1, W-MM8-PEM, W-MM8-PFO, S-CC3 and S-P5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, December 9, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 9, 2020

Figure 1: STA 15505+00 – Controls in place functioning properly. Area stabilized with straw.

☉ 86°E (T) ☉ 36°54'19"N, 79°28'21"W ±16ft ▲ 873ft



15505

Figure 2: Stream S-MM8 – Controls in place functioning properly around stream S-MM8.

☉ 107°E (T) ☉ 36°54'10"N, 79°28'7"W ±32ft ▲ 839ft



S-MM8

Figure 3: STA 15574+00 – Controls in place functioning properly. Area stabilized with straw.

☉ 112°E (T) ☉ 36°53'44"N, 79°27'9"W ±32ft ▲ 763ft



15574

Figure 4: STA 15593+00 – Controls in place functioning properly. Area stabilized with straw.

☉ 93°E (T) ☉ 36°53'39"N, 79°26'49"W ±32ft ▲ 782ft



15593