

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 3, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13906+50 – 13940+00 STA 13845+00 – 13892+00 MVP-FR-305/303.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II2, S-C16, S-C17, W-CD6, S-CD6 and W-CD5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, December 3, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 3, 2020

Figure 1: STA 13940+00 – Controls in place functioning properly. Area stabilized with straw.

☉ 97°E (T) ● 37°2'55"N, 79°54'3"W ±32ft ▲ 1124ft



13940

Figure 2: STA 13911+00 – Controls in place functioning properly.

☉ 319°NW (T) ● 37°3'1"N, 79°54'33"W ±32ft ▲ 1009ft



13911

Figure 3: STA 13853+00 – Controls in place functioning properly. Area stabilized with straw.

☉ 4°N (T) ● 37°3'31"N, 79°55'15"W ±16ft ▲ 1121ft



13853

Figure 4: STA 13860+00 – Controls in place functioning properly. Area stabilized with straw.

☉ 102°E (T) ● 37°3'31"N, 79°55'6"W ±3618ft ▲ 1133ft



13860