

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, December 1, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14649+67 – 14758+16 ATWS 367/533/535/368/536A/370	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling		Clearing/Grubbing		Grading		Trenching		Stri	inging/Welding		
	Lowering/Backfilling		Final Restoration		Temp. Stabilization		Perm. Stabilization	n 🗵 Dormant				
								Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes					
	Areas of of	fsite	sediment deposition ob	serve	d?				\boxtimes			
<u>Comments:</u> Inspected the following resources: S-H40, S-H39, W-H17, S-H37, W-H16, S-H36, W-H14, S-H34, S-H32, W-H11, S-H30, W-A8, S-A18, S-A19, S-H26, S-A20, S-H27 and S-A22. Recommended Corrective Action: N/A												
Deadline: N/A The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement												
	Inspector Signature: Date: Tuesday, December 1, 2020											



FIELD INSPECTION PHOTO LOG

<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Tuesday, December 1, 2020



Figure 3: STA 14707+00 – Controls in place functioning properly. Area stabilized with straw.



Figure 4: **STA 14745+00** – Controls in place functioning properly. Area stabilized with straw.

