

## FIELD INSPECTION REPORT

|                                  |                                                     |                  |                             |
|----------------------------------|-----------------------------------------------------|------------------|-----------------------------|
| Project Name:                    | Mountain Valley Pipeline                            | Inspector:       | Marshall Willis             |
| Inspection Date:                 | Friday, November 20, 2020                           | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I:<br>Pittsylvania County | STA 15370+62 – 15480+67<br>ATWS 492/493/548/549/494 | Weather:         | Dry                         |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G6, S-G5, S-G4, W-B3 and S-CC16.

Recommended Corrective Action: N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Friday, November 20, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, November 20, 2020

**Figure 1: STA 15372+00** – Controls in place and functioning properly. Area stabilized with straw.

☉ 85°E (T) ☉ 36°55'20"N, 79°30'37"W ±16ft ▲ 754ft



**Figure 2: STA 15397+00** – Controls in place and functioning properly. Area stabilized with straw.

☉ 307°NW (T) ☉ 36°55'9"N, 79°30'6"W ±32ft ▲ 852ft



**Figure 3: Stream S-G5** – Controls in place and functioning properly around S-G5 crossing. Area stabilized with straw.

☉ 105°E (T) ☉ 36°55'4"N, 79°29'49"W ±16ft ▲ 780ft



**Figure 4: STA 15465+00** – Controls in place and functioning properly. Area stabilized with straw.

☉ 116°SE (T) ☉ 36°54'43"N, 79°28'55"W ±16ft ▲ 870ft

