

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, November 19, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13992+00 – 14002+00 MVP-FR-306.02 ATWS 1466	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL36.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, November 19, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 19, 2020

Figure 1: Stream S-KL36 – Controls in place and functioning properly around S-KL36 crossing. Area stabilized straw.

☉ 36°NE (T) ☉ 37°3'11"N, 79°53'4"W ±32ft ▲ 947ft



Figure 2: STA 13996+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 49°NE (T) ☉ 37°3'10"N, 79°53'6"W ±16ft ▲ 1011ft



Figure 3: STA 13995+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 236°SW (T) ☉ 37°3'9"N, 79°53'6"W ±16ft ▲ 978ft

