

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 14, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12151+00 – 12200+00 MVP-MN-273/274/275	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C25, S-C24, S-C21 and S-OO11.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 12185+00: End-treatment repair needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, January 14, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 14, 2021

Figure 1: STA 12151+00 – Controls in place and functioning properly.

BRG: 280°W (T) **LAT:** 37.254931 **LON:** -80.271734 ±16ft **ALT:** 1555ft



Figure 2: STA 12171+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 114°SE (T) **LAT:** 37.253854 **LON:** -80.265220 ±16ft **ALT:** 1476ft



Figure 3: STA 12185+00 – End-treatment repair needed.

BRG: 194°S (T) **LAT:** 37.252346 **LON:** -80.260529 ±574ft **ALT:** 1349ft



Figure 4: STA 12200+00 – Controls in place and functioning properly.

BRG: 71°E (T) **LAT:** 37.252216 **LON:** -80.256866 ±32ft **ALT:** 1336ft

