

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, January 13, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County Pittsylvania County	STA 14981+55 – 15080+84 MVP-PI-325	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-D7, W-MM17, S-D3, S-D4, S-D2, W-D3, S-D1-INT and S-G11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, January 13, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 13, 2021

Figure 1: STA 14983+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 96°E (T) LAT: 36.965460 LON: -79.619959 ±32ft ALT: 938ft



Figure 2: STA 14997+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 95°E (T) LAT: 36.964498 LON: -79.615192 ±16ft ALT: 935ft



Figure 3: STA 15039+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 91°E (T) LAT: 36.965392 LON: -79.601543 ±213ft ALT: 849ft



Figure 4: Stream S-G11 – Controls in place and functioning properly.

BRG: 99°E (T) LAT: 36.962435 LON: -79.590815 ±16ft ALT: 902ft

