

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 12, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	MVP-RO-287/288 MVP-RO-286/281 STA 12994+02 – 13012+63	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-Q20, S-KL4, S-Z17, S-Y7, S-Y8, W-Y2 and S-EF32.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, January 12, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 12, 2021

Figure 1: MVP-RO-287 – Controls in place and functioning properly.

BRG: 189°S (T) **LAT:** 37.131537 **LON:** -80.135363 ±16ft **ALT:** 2689ft



Figure 2: MVP-RO-287 – Controls in place and functioning properly.

BRG: 69°E (T) **LAT:** 37.134497 **LON:** -80.137226 ±32ft **ALT:** 2632ft



Figure 3: MVP-RO-281 – Controls in place and functioning properly.

BRG: 355°N (T) **LAT:** 37.183882 **LON:** -80.146974 ±321ft **ALT:** 3222ft



Figure 4: STA 13012+00 – Controls in place and functioning properly.

BRG: 320°NW (T) **LAT:** 37.125968 **LON:** -80.125362 ±16ft **ALT:** 2725ft

