

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 11, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15221+11 – 15274+98 MVP-PI-328	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, January 11, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 11, 2021

Figure 1: STA 15222+00 – Controls in place and functioning properly.

BRG: 55°NE (T) **LAT:** 36.938535 **LON:** -79.554872 ±16ft **ALT:** 843ft



Figure 2: MVP-PI-328 – Controls in place and functioning properly.

BRG: 269°W (T) **LAT:** 36.937784 **LON:** -79.553644 ±213ft **ALT:** 846ft



Figure 3: STA 15250+00 – Controls in place and functioning properly.

BRG: 108°E (T) **LAT:** 36.935405 **LON:** -79.547375 ±16ft **ALT:** 793ft



Figure 4: ATWS 1522 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 152°SE (T) **LAT:** 36.934876 **LON:** -79.543841 ±16ft **ALT:** 799ft

