

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 7, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14250+00 – 14311+57 MVP-FR-313	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-F11, S-F9b, S-F10 and S-F9a.

Routine Maintenance: (*72-Hour Deadline from Notification*)

- STA 14251+00: Sump maintenance needed.
- STA 14251+50: Sump maintenance needed.
- STA 14251+75: Sump maintenance needed.
- STA 14252+00: Sump maintenance needed.
- STA 14252+50: Sump maintenance needed.
- STA 14252+00 to 14256+00: Re-stabilize ROW and stockpiles.

Ineffective Controls: (*24-Hour Deadline from Notification*)

- STA 14296+50: P1 repair needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, January 7, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 7, 2021

Figure 1: STA 14251+00 – Sump maintenance needed.

BRG: 337°NW (T) LAT: 37.052528 LON: -79.825225 ±16ft ALT: 919ft



Figure 2: STA 14251+50 – Sump maintenance needed.

BRG: 10°N (T) LAT: 37.052480 LON: -79.825202 ±16ft ALT: 918ft



Figure 3: STA 14251+75 – Sump maintenance needed.

BRG: 299°NW (T) LAT: 37.052446 LON: -79.825009 ±16ft ALT: 925ft



Figure 4: STA 14252+00 – Sump maintenance needed.

BRG: 68°NE (T) LAT: 37.052316 LON: -79.824957 ±16ft ALT: 918ft



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 7, 2021

Figure 5: STA 14252+50 – Sump maintenance needed.

BRG: 16°N (T) LAT: 37.052350 LON: -79.824744 ±16ft ALT: 954ft



Figure 6: STA 14252+00 to 14256+00 – Re-stabilize ROW and stockpiles.

BRG: 62°NE (T) LAT: 37.052344 LON: -79.824306 ±32ft ALT: 1001ft



Figure 7: STA 14296+50 – P1 repair needed.

BRG: 33°NE (T) LAT: 37.046902 LON: -79.812579 ±16ft ALT: 975ft

