

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, January 6, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13415+51 – 13487+00 STA 14010+58 – 14018+47 MVP-FR-293.02	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: SIJ4 and S-IJ8.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, January 6, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 6, 2021

Figure 1: ATWS 1351 – Controls in place functioning properly. Area stabilized with hydro-hulch.

BRG: 193°S (T) **LAT:** 37.046986 **LON:** -80.055578 ±12539ft **ALT:** 1297ft



Figure 2: STA 13425+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 123°SE (T) **LAT:** 37.091209 **LON:** -80.024411 ±16ft **ALT:** 1437ft



Figure 3: STA 13450+00 – Controls in place functioning properly. Area stabilized with straw.

BRG: 309°NW (T) **LAT:** 37.088265 **LON:** -80.016974 ±32ft **ALT:** 1712ft



Figure 4: STA 14017+00 – Controls in place functioning properly.

BRG: 243°SW (T) **LAT:** 37.057226 **LON:** -79.880501 ±32ft **ALT:** 1159ft

