

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, January 4, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12690+43 – 12713+62 MVP-RO-280 MVP-RO-281	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF32

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, January 4, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, January 4, 2021

Figure 1: Stream S-EF32 – Controls in place functioning properly along S-EF32 crossing.

BRG: 270°W (T) LAT: 37.180524 LON: -80.140107 ±16ft ALT: 2782ft



Figure 2: MVP-RO-281 – Controls in place functioning properly.

BRG: 85°E (T) LAT: 37.181850 LON: -80.145911 ±98ft ALT: 2945ft



Figure 3: STA 12692+00 – Controls in place functioning properly.

BRG: 126°SE (T) LAT: 37.148301 LON: -80.117286 ±5866ft ALT: 2710ft



Figure 4: STA 12709+00 – Controls in place functioning properly.

BRG: 153°SE (T) LAT: 37.190661 LON: -80.153099 ±98ft ALT: 3255ft

