

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 19, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14649+67 – 14758+16	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H38, W-H17, S-H37, W-H16, W-H15, S-H36, W-H14, S-H34, S-H32, W-H11, S-H30, W-A8, S-A18, S-A19/H26, S-A20, S-A27 and S-A22.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, January 19, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 19, 2021

Figure 1: STA 14651+00 – Controls in place and functioning properly.

BRG: 130°SE (T) **LAT:** 36.990737 **LON:** -79.723904 ±4179ft **ALT:** 976ft



14651

Figure 2: STA 14686+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 114°SE (T) **LAT:** 36.990351 **LON:** -79.724767 ±16421ft **ALT:** 924ft



14686

Figure 3: STA 14726+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 106°E (T) **LAT:** 36.987791 **LON:** -79.699674 ±32ft **ALT:** 881ft



14726

Figure 4: STA 14739+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 126°SE (T) **LAT:** 37.006506 **LON:** -79.711346 ±11772ft **ALT:** 833ft



14739