

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, February 26, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County Pittsylvania County	STA 13632+25 – 13660+00 STA 15470+00 – 15480+67	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E28 and S-GH3.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13655+50: Repair rill erosion and re-stabilize.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, February 26, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, February 26, 2021

Figure 1: STA 15480+00 – Controls in place and functioning properly. Area stabilized with straw mulch.

BRG: 320°NW (T) **LAT:** 36.910531 **Lon:** -79.477957 ±16ft **ALT:** 900ft



15480

Figure 2: STA 13646+00 – Controls in place and functioning properly.

BRG: 78°E (T) **LAT:** 37.071784 **Lon:** -79.970352 ±16300ft **ALT:** 1170ft



13646

Figure 3: STA 13655+50 – Repair rill erosion and re-stabilization needed.

BRG: 293°NW (T) **LAT:** 37.088413 **Lon:** -79.942770 ±12425ft **ALT:** 1191ft



Restabilize/repair rilling (72)

13655+50

Figure 4: STA 13639+00 – Controls in place and functioning properly. Area stabilized with hydro-mulch.

BRG: 302°NW (T) **LAT:** 37.088798 **Lon:** -79.962920 ±213ft **ALT:** 1251ft



13639