

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 17, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12190+25 – 12235+00 MVP-MN-275 MVP-MN-276.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-OO11 and S-C21.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, February 17, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 17, 2021

Figure 1: STA 12232+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.
BRG: 64°NE (T) LAT: 37.242268 LON: -80.213276 ±22967ft ALT: 1300ft



Figure 2: STA 12210+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.
BRG: 91°E (T) LAT: 37.253189 LON: -80.253902 ±334ft ALT: 1437ft



Figure 3: STA 12199+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.
BRG: 36°NE (T) LAT: 37.245846 LON: -80.258165 ±7129ft ALT: 1378ft



Figure 4: Stream S-C21 – Controls in place and functioning properly around Bradshaw Creek.
BRG: 196°S (T) LAT: 37.251870 LON: -80.259077 ±16ft ALT: 1270ft

