

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, February 11, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 13012+62 – 12994+02 STA 12687+28 – 12692+47 MVP-FR-293.01 MVP-RO-280	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, February 11, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 11, 2021

Figure 1: STA 13012+00 – Controls in place and functioning properly.

BRG: 332°NW (T) **LAT:** 37.126093 **LON:** -80.125195 ±98ft **ALT:** 2784ft



Figure 2: STA 12995+00 – Controls in place and functioning properly.

BRG: 96°E (T) **LAT:** 37.128563 **LON:** -80.130149 ±16ft **ALT:** 2638ft



Figure 3: STA 12691+00 – Controls in place and functioning properly.

BRG: 136°SE (T) **LAT:** 37.191534 **LON:** -80.157162 ±32ft **ALT:** 3698ft



Figure 4: MVP-RO-280 – Controls in place and functioning properly.

BRG: 151°SE (T) **LAT:** 37.184174 **LON:** -80.160544 ±32ft **ALT:** 3757ft

