

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 10, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14454+22 – 14546+75 MVP-FR-317.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G22, S-G23, S-G21, S-G20, S-G18 and S-G17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, February 10, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 10, 2021

Figure 1: STA 14456+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 123°SE (T) **LAT:** 37.026619 **LON:** -79.768267 ±16ft **ALT:** 1083ft



Figure 2: STA 14494+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 150°SE (T) **LAT:** 37.017888 **LON:** -79.760368 ±32ft **ALT:** 942ft



Figure 3: STA 14526+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 181°S (T) **LAT:** 37.010602 **LON:** -79.755250 ±357ft **ALT:** 1057ft



Figure 4: STA 14537+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 138°SE (T) **LAT:** 37.007728 **LON:** -79.754262 ±16ft **ALT:** 1053ft

