

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 9, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13060+00 – 13115+00 STA 13162+95 – 13185+40 MVP-FR-290/291/292/292.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G26 and S-G27.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, February 9, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 9, 2021

Figure 1: STA 13119+00 – Controls in place and functioning properly.

BRG: 80°E (T) **LAT:** 37.121735 **Lon:** -80.095072 ±98ft **ALT:** 2575ft



Figure 2: STA 13097+00 – Controls in place and functioning properly.

BRG: 254°W (T) **LAT:** 37.085336 **Lon:** -80.076702 ±24180ft **ALT:** 2853ft



Figure 3: STA 13073+00 – Controls in place and functioning properly.

BRG: 277°W (T) **LAT:** 37.125158 **Lon:** -80.126610 ±14049ft **ALT:** 3021ft



Figure 4: STA 13164+00 – Controls in place and functioning properly.

BRG: 71°E (T) **LAT:** 37.085275 **Lon:** -79.998617 ±18688ft **ALT:** 1618ft

