

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, February 8, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14273+62 – 14333+27 MVP-FR-313	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-F9b, S-F10, S-F9a and S-GG4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, February 8, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, February 8, 2021

Figure 1: STA 14305+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 156°SE (T) **LAT:** 37.045161 **LON:** -79.811333 ±32ft **ALT:** 1092ft



14305

Figure 2: STA 14289+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 323°NW (T) **LAT:** 37.048101 **LON:** -79.814262 ±32ft **ALT:** 1015ft



14289

Figure 3: STA 14330+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 145°SE (T) **LAT:** 37.038219 **LON:** -79.806660 ±541ft **ALT:** 1166ft



14330

Figure 4: STA 14322+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 309°NW (T) **LAT:** 37.041242 **LON:** -79.806329 ±16ft **ALT:** 1116ft



14322