

## FIELD INSPECTION REPORT

<b>Project Name:</b>	<b>Mountain Valley Pipeline</b>	<b>Inspector:</b>	<b>Marshall Willis</b>
<b>Inspection Date:</b>	<b>Friday, January 29, 2021</b>	<b>Project Contact:</b>	<b>Brian Clauto, Cory Chalmers</b>
<b>Spread I: Franklin County</b>	<b>STA 13541+50 – 13575+21 ATWS 1417/1416</b>	<b>Weather:</b>	<b>Snow</b>

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II9, S-II11, S-II12, S-GH6 and W-GH2.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Friday, January 29, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, January 29, 2021

**Figure 1: STA 13542+00** – Controls in place and functioning properly.

**BRG:** 66°NE (T) **LAT:** 37.091338 **LON:** -79.991108 ±32ft **ALT:** 1304ft



**Figure 2: STA 13548+00** – Controls in place and functioning properly.

**BRG:** 73°E (T) **LAT:** 37.091522 **LON:** -79.988911 ±32ft **ALT:** 1254ft



**Figure 3: Stream S-II11** – Controls in place and functioning properly.

**BRG:** 288°W (T) **LAT:** 37.092135 **LON:** -79.987278 ±328ft **ALT:** 1447ft



**Figure 4: STA 13563+00** – Controls in place and functioning properly.

**BRG:** 80°E (T) **LAT:** 37.091899 **LON:** -79.984339 ±164ft **ALT:** 1142ft

