

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 29, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13339+00 – 13350+00 STA 13310+50 – 13316+50	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, January 29, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, January 29, 2021

Figure 1: STA 13343+00 – Webster's Corner crossing looking NW. Controls in place and functioning properly. Area stabilized with erosion matting and straw.

BRG: 300°NW (T) **LAT:** 37.103827 **LON:** -80.043569 ±98ft **ALT:** 1600ft



Figure 2: STA 13344+00 – Webster's Corner crossing looking SE. Controls in place and functioning properly. Area stabilized with erosion matting and straw.

BRG: 116°SE (T) **LAT:** 37.103933 **LON:** -80.043129 ±16ft **ALT:** 1539ft



Figure 3: STA 13316+00 – Wades Gap crossing looking NW. Controls in place and functioning properly.

BRG: 330°NW (T) **LAT:** 37.106472 **LON:** -80.052026 ±328ft **ALT:** 1634ft



Figure 4: STA 13316+00 – Wades Gap crossing looking W. Controls in place and functioning properly.

BRG: 263°W (T) **LAT:** 37.106550 **LON:** -80.052396 ±32ft **ALT:** 1427ft

