

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, January 27, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14018+17 – 14062+17 STA 13996+56 – 14009+20 MVP-FR-306.02	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-YZ5, S-YZ4, S-KL39, S-KL36 and S-KL38.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14020+50: Re-stabilize MLV-31.

Ineffective Controls: (24-Hour Deadline from Notification)


- STA 14033+00: End-treatment CFS undermined.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, January 27, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 27, 2021

Figure 1: STA 14020+50 – Re-stabilize around MLV-31.

BRG: 267°W (T) LAT: 37.057779 LON: -79.880272 ±16ft ALT: 1092ft



Re-Stabilize mlv31

14020+50

Figure 2: STA 14033+00 – End-treatment undermined. Repair needed.

BRG: 36°NE (T) LAT: 37.060860 LON: -79.880593 ±16ft ALT: 1059ft



ET Undermined 24 ft

14033

Figure 3: STA 14052+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 54°NE (T) LAT: 37.065362 LON: -79.877455 ±16ft ALT: 1144ft



14052

Figure 4: STA 14028+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 139°SE (T) LAT: 37.060734 LON: -79.882386 ±328ft ALT: 1151ft



14028