

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 21, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15142+66 – 15210+25 MVP-PI-326	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-ST4, S-F1 and S-C7.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, January 21, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 21, 2021

Figure 1: STA 15146+00 – Controls in place and functioning properly.

BRG: 139°SE (T) **LAT:** 36.946750 **LON:** -79.577617 ±328ft **ALT:** 869ft



Figure 2: Stream S-C7 – Controls in place and functioning properly around stream C-C7 crossing.

BRG: 102°E (T) **LAT:** 36.944157 **LON:** -79.571789 ±16ft **ALT:** 711ft



Figure 3: STA 15175+00 – Controls in place and functioning properly.

BRG: 120°SE (T) **LAT:** 36.943223 **LON:** -79.569847 ±16ft **ALT:** 817ft



Figure 4: STA 15192+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 106°E (T) **LAT:** 36.940578 **LON:** -79.564471 ±32ft **ALT:** 833ft

