

FIELD INSPECTION REPORT

| | | | |
|--|---|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Wednesday, January 20, 2021 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H: Montgomery County | STA 12445+19 – 12544+27 MVP-MN-278.01 MVP-MLV-AR-28 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF19, W-KL58 and S-CD12b.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, January 20, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 20, 2021

Figure 1: STA 12537+00 – Controls in place and functioning properly. Area Stabilized with straw and erosion control fabric.
BRG: 312°NW (T) LAT: 37.211547 LON: -80.195502 ±98ft ALT: 1681ft



Figure 2: STA 12523+00 – Controls in place and functioning properly. Area Stabilized with straw and erosion control fabric.
BRG: 355°N (T) LAT: 37.197756 LON: -80.233750 ±9843ft ALT: 1787ft



Figure 3: STA 12513+00 – Controls in place and functioning properly. Area Stabilized with straw and erosion control fabric.
BRG: 178°S (T) LAT: 37.217770 LON: -80.197356 ±32ft ALT: 1934ft



Figure 4: STA 12488+00 – Controls in place and functioning properly. Area Stabilized with straw and erosion control fabric.
BRG: 156°SE (T) LAT: 37.226162 LON: -80.203033 ±8067ft ALT: 1537ft

