

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, October 9, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12001+72 – 12071+80 MVP-MN-270/268/268.01	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-PP23, W-PP8, S-G40, S-G39, S-G38 and S-G36.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Friday, October 9, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, October 9, 2020

**Figure 1: STA 12063+00** – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

☉ 152°SE (T) ☉ 37°15'36"N, 80°17'57"W ±32ft ▲ 2042ft



**Figure 2: STA 12053+00** – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

☉ 352°N (T) ☉ 37°15'43"N, 80°18'9"W ±32ft ▲ 2274ft



**Figure 3: MVP-MN-268.01** – PPL crews installing erosion control matting and applying temporary seed along MN-268.01.

☉ 231°SW (T) ☉ 37°16'4"N, 80°18'45"W ±32ft ▲ 1635ft



**Figure 4: Stream S-G36** – Controls in place and functioning properly around N. Fork Roanoke River crossing.

☉ 132°SE (T) ☉ 37°16'7"N, 80°18'52"W ±16ft ▲ 1573ft

