

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, October 8, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13730+00 – 13770+00 ATWS 568/1444/566	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF12 and S-EF7.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, October 8, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 8, 2020

Figure 1: STA 13750+00 – Controls in place and functioning properly.

☼ 131°SE (T) ● 37°4'28"N, 79°56'27"W ±32ft ▲ 1097ft



Figure 2: Stream S-EF12 – Controls in place and functioning properly around S-EF12 crossing.

☼ 106°E (T) ● 37°4'24"N, 79°56'25"W ±32ft ▲ 1112ft



Figure 3: STA 13760+00 – Controls in place and functioning properly.

☼ 107°E (T) ● 37°4'24"N, 79°56'18"W ±32ft ▲ 1100ft



Figure 4: ATWS 568 – Controls in place and functioning properly.

☼ 147°SE (T) ● 37°4'24"N, 79°56'22"W ±16ft ▲ 1067ft

