

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 7, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14546+75 – 14599+24 ATWS 362/363/530/1043/531	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-E18 and S-E17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, October 7, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 7, 2020

Figure 1: STA 14550+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 148°SE (T) ● 36°59'15"N, 79°44'15"W ±38922ft ▲ 1156ft



14550

Figure 2: STA 14560+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 310°NW (T) ● 37°0'9"N, 79°45'0"W ±16ft ▲ 970ft



14560

Figure 3: STA 14567+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 87°E (T) ● 37°0'7"N, 79°44'58"W ±10272ft ▲ 948ft



14567

Figure 4: STA 14572+00 – Controls in place and functioning properly. Area stabilized with straw.

☼ 95°E (T) ● 37°0'3"N, 79°44'48"W ±32ft ▲ 922ft



14572