

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, October 6, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12070+80 – 12119+17 STA 12151+28 – 12190+85 MVP-MN-270/273	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|-----------------------------------------------|--------------------------------------------|----------------------------------------------|----------------------------------------------|---------------------------------------------|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | | Yes | No | N/A |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO, S-F16a/b, S-C25 and S-C24.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 12073+00 to 12075+00: Re-stabilization needed.
- STA 12153+00 to 12154+00: Re-stabilization needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, October 6, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 6, 2020

Figure 1: STA 12070+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

☉ 325°NW (T) ☉ 37°15'30"N, 80°17'51"W ±32ft ▲ 1792ft



12070

Figure 2: STA 12073+00 to 12075+00 – Re-stabilization needed.

☉ 297°NW (T) ☉ 37°15'30"N, 80°17'49"W ±16ft ▲ 1791ft



12075+50

Figure 3: STA 12153+00 to 12154+00 – Re-stabilization needed.

☉ 49°NE (T) ☉ 37°15'17"N, 80°16'16"W ±16ft ▲ 1537ft



Restabilize

12153-154

Figure 4: STA 12171+00 – Controls in place and functioning properly. Area stabilized with erosion matting and straw.

☉ 93°E (T) ☉ 37°13'54"N, 80°15'27"W ±11211ft ▲ 1400ft



12171