

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, July 7, 2020	Project Contact:	Brian Clauto
Spread H: Montgomery	AR 276.03, 273 ATWS 1374, 1168, 1167 MP 232.5, 232.8, 232.4, 231.5, 230 Ironto laydown yard	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Grading | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

- Comments: Inspected the following resources: N/A
- ECD's were in place and appeared to be functioning, temporary stabilization has been established.

Routine Maintenance: (72-Hour Deadline from Notification)

- N/A

Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, July 7, 2020

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Tuesday, July 7, 2020


- Figure 1: Fueling station / protection is in place at the Ironto laydown yard.



- Figure 2: Near MP 232.5 temporary stabilization is in place.



- Figure 3: Near MP 232.8, pipe has been stockpiled, waterbars remain matted and temporary stabilization is in place.



- Figure 4: Near MP 231.5 ECD's and stabilization is in place and functioning.

