

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, June 25, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 12994+00 – 13063+00 MVP-FR-290 ATWS 954/1038/1039	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G26, S-G27, S-H1, S-G24, W-ST2-PEM, W-KL41, S-RR16, W-RR3, S-RR18 and W-RR4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, June 25, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, June 25, 2020

Figure 1: STA 13060+00 – Controls in place and functioning properly.

☉ 112°E (T) ● 37°7'37"N, 80°6'42"W ±16ft ▲ 2660ft



Figure 2: STA 13042+00 – Controls in place and functioning properly. Area stabilized with erosion fabric and vegetation.

☉ 83°E (T) ● 37°7'39"N, 80°7'2"W ±16ft ▲ 2645ft



Figure 3: STA 13026+00 – Controls in place and functioning properly. Area stabilized with vegetation and erosion control fabric.

☉ 274°W (T) ● 37°7'32"N, 80°7'14"W ±98ft ▲ 2709ft



Figure 4: STA 13020+00 – Controls in place and functioning properly. Area stabilized.

☉ 108°E (T) ● 37°7'31"N, 80°7'25"W ±16ft ▲ 2718ft

