

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 2, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13644+82 – 13748+30 ATWS 1067/1362/566	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GH4, S-GH3, S-GH2, S-E29, S-E28, W-E7, W-E8 and S-EF4.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 01/02/2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 2, 2020

Fig. 1: **STA 13644+82** – Leaning Oak Road Crossing. Controls in place and functioning properly.



Fig. 2: **STA 13662+00** – Controls in place and functioning properly. Area stabilized with Flexterra.



Fig. 3: **STA 13727+50** – Controls in place around Stream S-EF4 crossing. Area stabilized.



Fig. 4: **STA 13738+00** – Controls in place and functioning properly. Area stabilized with Flexterra.

