

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 24, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+51 – 13438+31 STA 13539+00 – 13543+00 STA 13562+63 – 13575+21 MVP-FR-293.02	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ10, W-IJ3, W-II8, S-II7, S-II9, S-GH6 and W-GH2.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, January 24, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, January 24, 2020

Figure 1: STA 13416+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 112°E (T) ☉ 37°5'32"N, 80°1'36"W ±32.8ft ▲ 1495ft



Figure 2: STA 13438+00 – Controls in place and functioning properly.

☉ 144°SE (T) ☉ 37°5'24"N, 80°1'11"W ±16.4ft ▲ 1698ft



Figure 3: STA 13541+00 – Controls in place and functioning properly.

☉ 270°W (T) ☉ 37°5'28"N, 79°59'29"W ±16.4ft ▲ 1283ft



Figure 4: STA 13574+00 – Controls in place and functioning properly.

☉ 235°SW (T) ☉ 37°5'34"N, 79°58'48"W ±16.4ft ▲ 1299ft

