

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 23, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12445+86 – 12544+27 MVP-MLV-AR-28 MVP-MN-278.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-CD12b, W-KL58 and S-EF19.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, January 23, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 23, 2020

Figure 1: STA 12532+00 – Controls in place and functioning properly. Area stabilized with straw, hydro-mulch and erosion matting.

☉ 148°SE (T) ☉ 37°12'44"N, 80°11'47"W ±98.4ft ▲ 1687ft



Figure 2: Stream S-EF19 – Controls in place and functioning properly.

☉ 220°SW (T) ☉ 37°12'56"N, 80°11'50"W ±32.8ft ▲ 1942ft



Figure 3: STA 12505+00 – Controls in place and functioning properly. Area stabilized with straw, hydro-mulch and erosion matting.

☉ 298°NW (T) ☉ 37°13'34"N, 80°12'20"W ±11431.0ft ▲ 1854ft



Figure 4: STA 12485+00 – Controls in place and functioning properly. Area stabilized with straw, hydro-mulch and erosion matting.

☉ 359°N (T) ☉ 37°13'30"N, 80°12'7"W ±16.4ft ▲ 1462ft

